



STOW POLICE DEPARTMENT
PRIVATE PROPERTY / MINOR TRAFFIC
CRASH REPORT

REPORT NO.
2021-00007603

Private Property
Minor Traffic

DO NOT USE THIS FORM FOR FATAL OR SERIOUS INJURY ACCIDENTS, OR FOR ACCIDENTS INVOLVING GOVERNMENT VEHICLES.

LOCATION OF ACCIDENT DARROW RD \ GRAHAM RD				CITY - TWP - VILLAGE Stow				DATE 5/19/2021	TIME 08:32
REPORT TAKEN <input type="checkbox"/> AT STATION <input checked="" type="checkbox"/> AT SCENE	NO. OF VEH PEDESTRIANS INVOLVED 02	ACCIDENT SEVERITY (CHECK MOST SEVERE) <input type="checkbox"/> INJURY <input checked="" type="checkbox"/> PROPERTY DAMAGE ONLY				COMBINED VEH/PROP LOSS <input type="checkbox"/> OVER \$150 <input type="checkbox"/> UNDER \$150	HIT SKIP	<input type="checkbox"/> SOLVED <input type="checkbox"/> UNSOLVED	
A UNIT NO. 01	NO. OF OCCUPANTS 01	OPERATING <input checked="" type="checkbox"/>	PARKED <input type="checkbox"/>	DRIVERLESS <input type="checkbox"/>	HIT & RUN <input type="checkbox"/>	NON-CONTACT <input type="checkbox"/>	INSURANCE CO. OR AGENT		
DRIVER-PEDESTRIAN NAME (LAST, FIRST, MI) MERCADO ORTIZ, ANGEL, LUIS				ADDRESS (NO., STREET, CITY, STATE, ZIP CODE) 4310 66TH ST BROOKLYN, OH 44144					
PHONE NO. [REDACTED]	BIRTH DATE M07 D27 1965	AGE 55	SEX M	SOCIAL SECURITY NO. [REDACTED]		STATE OH	DRIVER'S LICENSE NO. [REDACTED]	OCCUPATION	
OWNER (IF SAME AS DRIVER, WRITE SAME) American Construction Group, LTD,				ADDRESS 6337 Chittenden RD Suite B Hudson, OH 44236				PHONE [REDACTED]	
VEH YR 2018	MAKE Chevrolet	MODEL	COLOR WHI	STYLE	STATE OH	LICENCE PLATE NO. PKU9166	TOWING SERVICE	VEH/PED DIR FROM N TO S	
CIRCLE DAMAGE AREAS 	9 TOP 10 UNDERCAR 11 LOAD 12 TRAILER	DAMAGE SEVERITY <input checked="" type="checkbox"/> NON-FUNCTIONAL <input type="checkbox"/> FUNCTIONAL <input type="checkbox"/> DISABLING		DAMAGE SCALE <input type="checkbox"/> NONE <input type="checkbox"/> MODERATE <input checked="" type="checkbox"/> LIGHT <input type="checkbox"/> HEAVY		VEHICLE DISPOSITION <input checked="" type="checkbox"/> DRIVEN AWAY <input type="checkbox"/> REMAINED AT SCENE <input type="checkbox"/> TOWED		FIRE <input checked="" type="checkbox"/> NO FIRE <input type="checkbox"/> FIRE DUE TO CRASH <input type="checkbox"/> OTHER FIRE	
B UNIT NO. 02	NO. OF OCCUPANTS 01	OPERATING <input checked="" type="checkbox"/>	PARKED <input type="checkbox"/>	DRIVERLESS <input type="checkbox"/>	HIT & RUN <input type="checkbox"/>	NON-CONTACT <input type="checkbox"/>	INSURANCE CO. OR AGENT Acceptance		
DRIVER-PEDESTRIAN NAME (LAST, FIRST, MI) BLACKSTON, DEREK, L				ADDRESS (NO., STREET, CITY, STATE, ZIP CODE) 170 S THOMAS RD TALLMADGE, OH 44278					
PHONE NO. [REDACTED]	BIRTH DATE M06 D08 1985	AGE 35	SEX M	SOCIAL SECURITY NO. [REDACTED]		STATE OH	DRIVER'S LICENSE NO. [REDACTED]	OCCUPATION	
OWNER (IF SAME AS DRIVER, WRITE SAME) BLACKSTON, DEREK, L				ADDRESS 170 S THOMAS RD TALLMADGE, OH 44278				PHONE [REDACTED]	
VEH YR 2018	MAKE Kia	MODEL	COLOR SIL	STYLE SW	STATE OH	LICENCE PLATE NO. GHM5437	TOWING SERVICE	VEH/PED DIR FROM N TO S	
CIRCLE DAMAGE AREAS 	9 TOP 10 UNDERCAR 11 LOAD 12 TRAILER	DAMAGE SEVERITY <input checked="" type="checkbox"/> NON-FUNCTIONAL <input type="checkbox"/> FUNCTIONAL <input type="checkbox"/> DISABLING		DAMAGE SCALE <input type="checkbox"/> NONE <input type="checkbox"/> MODERATE <input checked="" type="checkbox"/> LIGHT <input type="checkbox"/> HEAVY		VEHICLE DISPOSITION <input checked="" type="checkbox"/> DRIVEN AWAY <input type="checkbox"/> REMAINED AT SCENE <input type="checkbox"/> TOWED		FIRE <input checked="" type="checkbox"/> NO FIRE <input type="checkbox"/> FIRE DUE TO CRASH <input type="checkbox"/> OTHER FIRE	
A <input type="checkbox"/> O.R.C. OFFENSE CHARGED (IF APPLICABLE) <input type="checkbox"/> CITY ORD:				B <input type="checkbox"/> O.R.C. OFFENSE CHARGED (IF APPLICABLE) <input type="checkbox"/> CITY ORD:					

REMARKS

Unit #1 was southbound on Darrow Rd (SR 91) stopped for the red light at the intersection of Graham Rd. Unit #2 was southbound on Darrow and failed to stop, striking unit #1 from behind. There was minor damage to both vehicles (unit #1 had a bent rear step bumper and the front license plate on unit #2 was bent, along with some scrapes on the front bumper).

DATE FILED 05/19/2021	ARRIVED 08:32	CLEARED 09:20	OTHER 30	TOTAL TIME 78	PRE-ACCIDENT ACTIONS	A 4	B 1
					1. GOING STRAIGHT 2. TURNING 3. PARKING/UNPARKING 4. STOPPED	5. PARKED 6. BACKING 7. PEDESTRIAN ACTIONS 8. OTHER DRIVER ACTION	

(Include brief description, injuries, tow, any pertinent information.)

DRUMMOND
OFFICER (S)

710
I.D. (S)

DRUMMOND
SUPERVISOR APPROVING

710

The Financial Responsibility Law requires the owner or operator of a motor vehicle that is involved in an accident causing injury, death, or damage to property of any one person in excess of \$1000 to make a report within 30 days to the State of Ohio, Bureau of Motor Vehicles, Safety Responsibility Division, Columbus, Ohio 43216. Failure to do so may result in loss of your Drivers License.



Graham Rd



Darrow Rd (SR 91)

NOT
DRAWN TO
SCALE