



# STOW POLICE DEPARTMENT

PRIVATE PROPERTY ACCIDENT REPORT/MINOR  
TRAFFIC ACCIDENT REPORT

INCIDENT NUMBER  
**24-10129**

DATE  
**6.24.24**

TIME  
**1751**

Private Property  Private Property - Hit/Skip  Minor Traffic Accident

LOCATION - ADDRESS  
**3520 HUDSON DR. (WALMART)**

**VEHICLE #1**

DRIVER #1 - NAME (Last, First, Middle) **UNK** PHONE

ADDRESS CITY STATE ZIP

SSN DATE OF BIRTH DRIVER'S LICENSE NUMBER STATE

OWNER #1 - NAME (Last, First, Middle)  SAME AS DRIVER #1 **UNK** PHONE

ADDRESS CITY STATE ZIP

SSN DATE OF BIRTH DRIVER'S LICENSE NUMBER STATE

VEHICLE LICENSE# STATE YEAR MAKE MODEL COLOR

INSURANCE COMPANY POLICY NUMBER

PARTS OF VEHICLE DAMAGED CONTRIBUTING CIRCUMSTANCES

**VEHICLE #2**

DRIVER #2 - NAME (Last, First, Middle) PHONE

ADDRESS CITY STATE ZIP

SSN DATE OF BIRTH DRIVER'S LICENSE NUMBER STATE

OWNER #2 - NAME (Last, First, Middle)  SAME AS DRIVER #2 **LINGDEN, BUDDHA, BIR** PHONE

ADDRESS **434 ROANOKE AVE** CITY **CUYAHOGA FALLS** STATE **OH** ZIP **44221**

SSN **[REDACTED]** DATE OF BIRTH **5.23.74** DRIVER'S LICENSE NUMBER **[REDACTED]** STATE **OH**

VEHICLE LICENSE # STATE YEAR MAKE MODEL COLOR  
**KER 6242 OH 2023 TOYOTA RAV - 4 WHITE**

INSURANCE COMPANY POLICY NUMBER  
**TRAVELER'S 6109 76730 203 1**

PARTS OF VEHICLE DAMAGED CONTRIBUTING CIRCUMSTANCES  
**DRIVER SIDE REAR QUARTER PANEL + BUMPER NONE**

DESCRIBE WHAT HAPPENED

**UNIT 2 WAS PARKED UNOCCUPIED IN THE WALMART PARKING LOT. WHEN THEY CAME OUT OF THE STORE THEY SAW THE REAR OF THE CAR WAS DAMAGED.**


See Reverse Side for Diagram

SUBMITTED BY: **OFC. MARUNIA #755** DATE **6.27.24**

APPROVING OFFICER: **[Signature]** DATE **6/24/24**

# STOW POLICE DEPARTMENT

## FIELD SKETCH (not drawn to scale)



### WEATHER

- CLEAR
- RAIN
- SNOW
- FOG
- OTHER

### LIGHT

- DAYLIGHT
- DAWN
- DUSK
- DARK - LIGHTED ROAD
- DARK - NOT LIGHTED
- DARK - UNK LIGHTING
- UNKNOWN

### SURFACE

- DRY
- WET
- SNOW
- ICE
- OTHER

### ROAD

- CONCRETE
- BLACKTOP
- DIRT
- OTHER